

Machine History

MAKE & MODEL	SERIAL NUMBER	FLEET NUMBER
EC700	110197	1199

PURCHASE DATE:	09/11/12
KEY CODE 0197	
<u>BUCKET INFO</u>	SERIAL NO- 01962
	SSAB 15078383
	2200MM WIDE HI SPEC
	CAPACITY 4.4M3
	WEIGHT – 4680KG
	COMBI C6 X 5
120ID X 140OD X 72MM	PRESS IN BUSHES IN BUCKETS. HITACHI PART NO 4439033

DATE	HOURS	ACTION COMPLETED	W/S NUMBER
09/11/12		REFITTED RAM TO DIPPER PIN. AND FITTED BUCKET	LIAM - 34445
30/11/12		BUCKET AND DIPPER PIN REMOVED. MACHINE RETURNED TO YARD FOR REPAIR. (DIPPER BOSS L/H CANT GET GREASE.	
09/12/12	136	REPAIRS TO MACHINE. BREATHER PIPE ON DIESEL TANK BLANKED OFF AND REPOSITIONED. DIPPER REMOVED FROM MACHINE HINGE BUSHES REMOVED AND DIPPER INLINE BORED NEW BUSHES FITTED GREASER BLOCK REPOSITIONED ON DIPPER. MACHINE REASSEMBLED ALL OK	VOLVO – STEVEM - 34910
15/01/13	311	250 HRS SERVICE - FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. LEVELS OK. COOLANT CHECKED ANTIFREEZE -46 BATTEREYS OK. GREASE POT TOPPED UP. LIGHTS OK.	MARK L- 35438
09/02/13	461	REPLACED O RING ON LARGE BUNG. IN RH BOOM RAM CHECK VALVE	LIAM - 35757
14/02/13	493	VOLVO- BUCKET CROWD DOWN ON POWER. REMOVE MCV COVER OVER SET MAIN RELIEF VALVE CHECK PRESSURES. SET TO MAX PRESSURE.	VOLVO=-
23/02/13	559	500 HRS SERVICE - ENG OIL CHANGED OIL FILLED 75 % FULL. FILTERS CHANGED ENG FUEL. AIR AND CAB FILTERS BLOWN OUT. LEVELS OK COOLANT CHECKED ANTIFREEZE-E46. BATTEREYS OK. MACHINE GREASED AND GREASE POT FILLED. LIGHTS OK SAMPLE ENG AND HYD	MARK L= 35662
28/02/13	565	VOLVO = COOLANT LEAK. TIGHTEN HOSE CLIPS. REASS	VOLVO-
09/04/13	859	750 HRS SERVICE - FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT AND CAB FILTERS. LEVELS OK ENG TOPPED UP. COOLANT TOPPED UP ANTIFREEZE – 46 BATTEREYS CHECKED. GREASE POT TOPPED UP. LIGHTS OK	MARK L= 35994
04/03/13	719	VOLVO = ENG PREHEATER FAULT. TEST ELECTRICAL CIRCUITS. REFIT PANELS.	VOLVO
16/03/13	719	VOLVO = ENG PREHEATER FAULT. REMOVE FAN GUARD AND REMOVE INLET ENG HEATER TEST FIT NEW UNIT	VOLVO-
24/05/13	1161	1000 HRS SERVICE - ENG OIL CHANGED SLEW AND FINAL DRIVES. FILTERS CHANGED ENG FUEL HYD AIE CAB AND BREATHERS. COOLANT OK -46 HYD TOPPED UP. GREASE POT TOPPED UP. TRACKS PUMPED UP. RADS BLOWN OUT. LIGHTS OK SMAPLE ENG HYD SLEW AND FINAL DRIVES	MARK L- 36880
09/07/13	1460	250 HRS SERVICE - FUEL FILTERS CHANGED. AIR CAB FILTERS BLOWN OUT. LEVELS OK ENG TOPPED UP. COOLANT TOPPEDUP -46 BATTEREYS OK GREASE POT TOPPED UP. LIGHTS OK SAMPLE HYD	MARK L- 36491

Machine History

06/08/13	1592	REPLACED BUCKET TEETH	LIAM - 35838
28/08/13	1722	500 HRS SERVICE - ENG OIL CHNAGED. FILTRS ENGF AND FUEL. AIR AND CAB FILTERS BLOWN OUT. LEVELS OK HYD AND SLEW TOPPEDU P. COOLANT TOPPED UP – 46. BATTEREYS OK MACHINE GREASED GREASE POT TOPPED UP. LIGHTS OK SAMPLE END AND HYD	MARK L- 37391
09/09/13		REPLACED BROKEN GREASED PIPES	STEVE L- 37422
10/10/13	2008	1000HRS SERVICE - ENG OIL CHNANGED SLEW FD. FILTERS ENG FUEL HYD AIR CAB AND BREATHERS. LEVELS OK HYD TOPPED UP. COOLANT OK -46. BATTEREYS OK. MACHINE GREASED AND GREASE TOPPED UP. LIGHTS OK SAMPLE ENG HYD SLEW FD	MAR KL- 37573
26/11/13	2294	250 HRS SERVICE = FUEL FILTERS CHNAGED AIR FILTERS BLOWN OUT. LEVELS OK ENG AND HYD TOPPED UP. COOLANT OK -46 BATTEREYS OK. MACHINE GREASED. GREASE POT TOPPED UP. LIGHTS OK	MAR KL = 38750
30/10/13	2132	REPLACED TEETH	LIAM - 37189
21/01/14	2568	500 HRS SERVICE = ENG OIL CHNAGED FILTERS ENG AND FUEL. AIR FILTERS BLOWN OUT. LEVELS OK HJYD TOPPED UP. COOLANT OK -46 BATTEREYS OK. MACHINE GREASED AND GREASE POT TOPPED UP. LIGHTS OK SAMPLE ENG AND HYD	MARK L- 38847
14/03/14	2849	750 HRS SERVICE = FUEL FILTERS CHNAGED. AIR AND CAB FILTERS BLOWN OUT. LEVELS OK ENG TOPPED UP. COOLANT OK – 32 BATTEREYS OK. MACHINE GREASED AND GREASE POT TOPPED UP. LIGHTS OK GREEN BEACON BELT US. NEEDS NEW GREEN BEACON	MARK L- 39897
09/04/14		CHECK MC GREEN LIGHT WIRING FAULT TO BE DONE	STEVE L- 39515
28/04/14	3089	1000 HRS SERVICE = ENG OIL CHNAGED SLEW AND FD. FILTERS ENG FUEL AIR CAB AND BREATHERS. LEVELS OK. HYD TOPPED UP. COOLANT TOPPED UP – 46 BATTEREYS OK. MACHINE GREASED. LIGHTS OK SAMPLE ENG HYD SLEW AND FD	MARK L- 39931
19/06/14	3365	250 HRS SERVICE = FUEL FILTERS HCNAGED. AIR FILTERS BLOWN OUT. LEVELS OK ENG AND HYD TOPPED UP. COOLANT OK – 32 BATTEREYS OK. MACHINE GREASED AND GREASE POT TOPPEDUP. LIGHTS OK SEAT BELT GREEN BEACON US. NOT THE BEACON SEEMS LIKE SEAT BELT CONNECTOR SWITCH	MARK L- 40547
04/08/14	3601	500 HRS SERVICE – ENGINE OIL CHANGED – FILLED WITH 10/30. FILTERS CHANGED – ENG AND FUEL. AIR FILTER BLOWN OUT. OIL LEVELS CHECKED. COOLANT CHECKED – ANTI FREEZE READING = -32DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED. SAMPLES TAKEN – ENG AND HYD.	MARK L - 40803
		750 HRS SERVICE – FUEL FILTER CHANGED. AIR FILTERS BLOWN OUT. CAB FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG AND SLEW ×2 TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING =-32DEG. BATTERIES CHECKED. GREASE POT FILLED. LIGHTS CHECKED.	MARK L - 41080
16/09/14	3804	WELD REPAIRS ON SEAT, REMOVE MIRROR ARM AND WELD UP AND STRENGTHEN. REPLACE TURBO OUT PIPE TO INTERCOOLER. REPAIRS TO WASHER PUMPS.	MARK H - 39693
21/10/14	2991	CHECK OUT MACHINE. 9 TRACK PADS LOOSE. NO HYD LEAK. NO ENG LEAKS. BUCKET GOOD. COSMETICALLY SOUND.	D KING - 39331
05/11/14	4081	1000 HRS SERVICE – OIL CHANGED – ENG, SLEW ×2 AND FINAL DRIVE ×2. FILTER CHANGED – ENG, FUEL, HYDS, AIR, CAB AND BREATHERS. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING =-32DEG. BATTERIES CHECKED. MACHINE GREASED AND GREASE POT TOPPED UP. LIGHTS CHECKED. SAMPLES TAKEN – ENG, HYD, SLEW × 2 AND FINAL DRIVE ×2. ENGINEER COMMENTS: NEEDS 1 × NEW DRAIN BUNG FOR LEFT SIDE FINAL DRIVE (LOOKS LIKE ITS BEEN DAMAGED BY ROCK).	MARK L - 41601
04/5/11/14	4081	REPLACE SEAT RUNNERS × 4 AND BASE UNIT. (WORN OUT) REPLACE	MITCH/ MARK H –

Machine History

		VARIOUS TRACK PAD BOLTS ×20. ETC.	41418
22/12/14	4313	250 HRS SERVICE – FUEL FILTERS CHANGED. AIR FILTER BLOWN OUT. OIL LEVELS CHECKED – ENG AND RIGHT SLEW TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED.	MARK L – 41917
23/12/14	4313	REPLACE TRACK PAD BOLTS. REPLACE STARTER MOTOR.	MARK/MITCH – 41431
27/02/15	4600	500 HR SERVICE – ENGINE OIL CHANGED. FILTERS CHANGED – ENG & FUEL. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED. SAMPLES TAKEN – ENG & HYD.	MARK LINES – 42678
17/03/15	4706	CHECK FOR TRACK PINS OUT, UNABLE TO MOVE THEM.	P HARTLEY - 42648
15/04/15	4868	750 HR SERVICE: FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG & LIGHT SLEW TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED.	MARK LINES – 43477
26/05/15	5087	WELD & REPAIR, MAKE BRACKET UP FOR MIRROR ARM.	P HARTLEY - 43910
11/06/15	5120	TIGHTEN PAD BOLTS. REPLACE FRONT WIPER BLADE.	P HARTLEY - 43928
11/06/15	5170	1000 HR SERVICE: OIL CHANGED – ENG, SLEW X 2, & FINAL DRIVE X 2. FILTERS CHANGED – ENG, FUEL, HYD'S, AIR, & CAB BREATHER. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED. SAMPLES TAKEN – ENG, HYD, SLEW X 2, & FINAL DRIVE X 2.	MARK LINES – 43844
03/07/15	5285	CHECK FOR SCREEN WASH FAULT. TRACE FAULT TO PUMP – CLEAN SCREEN WASH WORKING BUT REQUIRES NEW PUMP.	P HARTLEY – 44265
07/07/15	5293	REPLACE SCREEN WASH PUMP.	P HARTLEY - 44269
27/07/15	5410	250 HR SERVICE: FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED.	MARK LINES – 44655
06/08/15	=	REPLACE FINAL DRIVE LEVEL BUNG. MEASURE BUCKET.	P HARTLEY – 44609
14/08/15	5501	WELD & REPAIR MIRROR ARM.	P HARTLEY – 44626
18/09/15	5683	500 HR SERVICE: ENGINE OIL CHANGED. FILTERS CHANGED – ENG & FUEL. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP.	MARK LINES – 46480

Machine History

		LIGHTS CHECKED. SAMPLES TAKEN – ENG & HYD.	
13/10/15	5814	REPLACE 2 TRACKS. SWAP BUCKETS. FIT BUCKET NO: 375 TO MACHINE.	P HARTLEY & S MARSH - 46744
05/11/15	5944	750 HR SERVICE: FUEL FILTERS CHANGED. AIR FILTERS KNOCKED OUT. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED.	MARK LINES – 46882.
30/10/15	5918	REMOVE BONNET, REFIT BONNET AFTER REFERB.	M HILLMAN – 44482.
23/12/15	6199	1000 HR SERVICE: OIL CHANGED – ENG, SLEW X 2 AND FINAL DRIVE X 2. FILTERS CHANGED – ENG, FUEL, HYD'S, AIR, CAB, & BREATHERS. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED. SAMPLES TAKEN – ENG, HYD, SLEW X 2, AND FINAL DRIVE X 2.	MARK LINES – 45640.
19/02/15	6466	250 HR SERVICE: FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG & HYD TOPPED UP. COOLANT TOPPED UP. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED.	MARK LINES – 45743.
02/03/16	6532	CHECK FOR TRACK FAULT. TIGHTEN TRACKS. CARRY OUT INSOECTION. STRAIGHTEN TRACK FRAME STEPS.	P HARTLEY – 45968.
16/03/16	6618	REFIT STEPS TO TRACK FRAME. CRACK ON BOOM. REPORTED & DRIVER TO OBSERVER.	P HARTLEY – 45997.
04/04/16	6695	REMOVE & REPLACE STARTER MOTOR. REMOVER COVER FROM BELL HOUSING & REMOVE DAG. REMOVE DOOR LOCK ON PUMP SIDE & REPAIR DOOR LOCK. REPLACE BOLTS ON CAT WALK.	P HARTLEY – 47620.
08/04/16	6726	500 HR SERVICE: ENGINE OIL CHANGED. FILTERS CHANGED – ENG & FUEL. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED SAMPLES TAKEN- ENGINE HYDRAULIC	M. LINES- 47695
08/04/16	6726	REMOVE DAMAGED COUNTER WEIGHT BOLT. FIT NEW & TORQUE.	P HARTLEY – 47635.
09/05/16	6877	REMOVE TRACK ROLLERS X 2. REMOVE 5 BROKEN STUDS. REFIT ROLLERS WITH NEW BOLTS. TAP & CLEAN THREADS. STRAIGHTEN TRACK STEPS. ENG COMMENTS: NEW SCREEN WASH TOP REQ.	P HARTLEY - 48096

Machine History

17/05/16	6927	REMOVE / REPLACE BUCKET. REPAIRS TO TRUST PLATE. O RING BACK BUSH DIPPER. REMOVE BROKEN BOLTS X 2. RE-FIT THRUST PLATE ETC. REPLACE FUEL BOLE ON PRIMARY FILTER HEAD. REPAIRS TO GREASE PIPES ON PUSH LINK.	M HILLMAN & B WADE – 48604.
08/06/16	7035	750 HR SERVICE: FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG & HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED.	MARK LINES – 48720.
17/06/16	7083	REPLACED ENGINE ROCKER COVER, CLEANED THREADS AND BOLTED R/N/S ENGINE MOUNT BACK IN PLACE TO PALIFIC TOURQUE SETTINGS, TEST RUN ALL OK.	NICK PENYN – 48391.
20/06/16	7091	FIT NEW ALTERNATOR BELT & NEW FAN BELT.	R MERRYDEW – 48677.
22/07/16	7274	1000 HR SERVICE: OIL CHANGED – ENG, SLEW X 2 AND FINAL DRIVE X 2. FILTERS CHANGED – ENG, FUEL, HYD'S, AIR, CAB, & BREATHERS. OIL LEVELS CHECKED – HYD TOPPED UP. COOLNT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED. SAMPLES TAKEN – ENG, HYD, SLEW X 2, AND FINAL DRIVE X 2.	M LINES – 49383
12/08/16	7377	REPLACE BUCKET. REMOVE BROKEN BOLTS ON WEAR PLATE.	M HILLMAN – 48625.
22/07/16	7275	REPLACE BUCKET.	M HILLMAN – 48621.
18/08/16	7410	TEMP REPAIR TO WASHER PIPE. STRAIGHTEN STEPS. STRAIGHTEN CAB BELLY PLATE. ENG COMMENTS: NEW PIPE REQ.	P HARTLEY – 49753.
15/09/16	7554	250 HR SERVICE: FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -21 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED.	MARK LINES – 49812.
27/09/16	7623	CHECK AROUND. GRAB HANDLE TO BE WELDED & CENTRE BELLY PLATES REQ STRAIGHTENING (DATE TO BE ARRANGED).	P HARTLEY – 49962.
28/10/16	7793	SAMPLED ENG AND HYD OIL. 500 HR SERVICE: CHANGED FUEL & ENGINE OIL FILTERS. CHANGED ENGINE OIL. REPAIRED REAR RIGHT HAND STEP.	L MULLINS – 50560.
11/11/16	7868	REMOVE / REPLACE BUCKET. REPAIRS TO STEPS.	M HILLMAN – 51302.
29/11/16	7956	CHECK FOR COOLANT LEAK. REPLACE SECTION OF HEATER HOSE ON ENGINE. TOP UP COOLNT &	P HARTLEY – 50978.

Machine History

		TEST. REPLACE BOLT ON ALTERNATOR. TIGHTEN GRAB RAIL ON TOP OF ENGINE.	
06/01/17	8079	CARRY OUT 250 HR SERVICE: TIGHTEN CLAMPS ON BOXING RING. REPLACE 2 X HEATER HOSES. TIGHTEN BOXING RINGS. REPLACE ALTERNATOR BELT. REMOVE CENTRE BELLY PLATES & STRAIGHTEN & REFIT. REPLACE EXH CLAMP. REMOVE KICK GUARD ON BOXING RING, WELD & REPAIR. REMOVE STEPS BEHIND DRIVERS CAB & WELD & REPAIR.	P HARTLEY & D SHOWERING – 51468.
21/02/17	8333	CHECK FOR STARTING FAULT. CHECK BATTERIES. REMOVE STARTER, DOG FELL OFF. FIT NEW STARTER STILL NO START. NEW STARTER RELAY FAULTY. FIT OLD RELAY – ALL = OK. REPAIR GREASE PIPES ON BUCKET.	P HARTLEY – 51942.
27/02/17	8358	CHECK FOR ENGINE OIL PRESSURE FAULT. MANUALLY CHECK PRESSURE ALL OK. FIT NEW SENDER (NO CHANGE). SWAP C/C PRESSURE FOR ENGINE OIL PRESSURE – ALL OK. ENG COMMENTS: OIL PRESSURE SENDER REQ.	P HARTLEY & M HILLMAN – 53806.
08/03/17	8390	FINISH OFF 1000 HR SERVICE: OIL CHANGED – SLEW X 2 AND FINAL DRIVE X 2. OIL LEVELS CHECKED – ENG TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. AIR FILTERS BLOWN OUT. LIGHTS CHECKED. SAMPLES TAKEN – SLEW X 2, AND FINAL DRIVE X 2. FUEL TANK BREATHER FITTED. ENG OIL, & FILTERS, HYD OIL, & FILTERS, FUEL FILTERS CHANGED LAST WEEK BY: M HILLMAN & P HARTLEY.	MARK LINES – 52238.
14/03/16	8364	REMOVE / REPLACE REMAN ENGINE. ENGINE OIL CHANGED. FILTERS CHANGED – ENG, AIR, HYD, & FUEL. TAKE OIL SAMPLES. CHANGE ALL 1000 HOURLEY FILTERS, & RUN CHECK ETC.	M HILLMAN – 51329.
03/04/17	8502	REPAIR UNDER GUARD UNDER CAB. REPAIRS TO TRACK FRAME STEPS STRAIGHTEN & REMOVE BROKEN BOLTS ETC, & FIT NEW.	M HILLMAN – 51340.
12/05/17	8701	250 HR SERVICE: FUEL FILTERS CHANGED. OIL LEVELS CHECKED. AIR FILTERS BLOWN OUT. COOLANT CHECKED – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED. ENG COMMENTS: STEP BY R/H SIDE FINAL DRIVE BENT & CRACKED. NEEDS WELDING.	RICH & MARK – 54389.
19/05/17	8743	REPLACE BATTERIES & TEST CHARGING CORRECTLEY. (INDUCTION TO SITE ALSO) REMOVE SIDE STEP AS DAMAGED.	W BARTLETT – 54411.

Machine History

23/05/17	8758	TESTED SYSTEM LOW ON GAS. RECOVERED 272G OF GAS. VACUME TEST FOR 25 MINS. RECHARGED AT 1000G OF GAS REVOCERED 4ML OF OIL. REFILLED 4ML OF OIL. CLEANED OUT CONDENSOR WITH AIR LINE TESTED – ALLOK.	NICK PENNY – 54857.
28/06/17	8941	CARRY OUT 500HR SERVICE CHECK ALL OTHER LEVELS “LIGHTS. BLOW OUT AIR FILTER TIGHTEN CLIP ON WATER PIPE SAMPLE OILS (ENG – HYDO)	R MERRYDEW - 54078
15/07/17	9035	REPLACE ‘O’ RIGS X3 ON SWING MOTORS CRACK WELDING REPAIRS ON BOOM (DAVE BROWER) CHECK ROUND ETC.	M. MILLMAN - 54525
26/07/17	9087	REPLACE BOLT IN BUCKET RUSH LINK RE ASSBLE ECT RUN TEST	M.MILLMAN - 54530
08/09/17	9338	750HR SERVICE REPLACED FUEL FILTERS AND CHECKED LIGHTS AND REPLACED FUEL FILTERS & CHECKED LIGHTS + LEVELS REPAIRES TO SEAT (FOR BOLT FOR CRUSHER SLIDER) RE-MOUNTED RADIO IN CAB	L.MULLINS - 54725
23/09/17	9428	REMOVED BUCKET FOR REPAIR FIT SPARE BUCKET RE SEAL MOUNTING FACE ON SERUD PUMP REPLACED SUCTION HOSE ON HYD OIL COOLER OUTLET	L. MULLINS - 54738
18/10/17	9571	REPLACE MAIN BUCKET. REPAIR TO GREASE PIPES REPLACE O RINGS IN LH SLEW MOTOR PIPES X5 REPLACE INLET HEATER IN INLET MAINFOLD CHECK ROUND.	M. HILLMAN - 55517
01/11/17	9643	REMOVE/ REPLACE 2 SPEED TRACKING PIPE MOTOR TO CONTER JOINT TOP UP OIL 10 WELD REPAIRS TO REAR DOOR FRAME REPLACE/ SET UP DOOR CATCH	M.HILLMAN - 55524
03/11/17	9649	INSPECTED AC SYSTEM FOUND CONDENSOR + OIL COOLER BEHIND IT BLOCKED WITH DUST TOOK APART CLEANED OUT PUT BACK TOGETHER TEST FOR ½ HOUR ALL WORKING OK + CLEANED OUT CAB FILTER. PUT NEW RUBBERS IN BOXING RING LINKS + TIGHTENED UP LOWER RUBBER MOUNTS, ADJUSTED N/S REAR DOOR LOCK MECH CLEANED OUT MAIN COOLANT RADIATOR, FITTED 3 X NEW STEPS ON TRACK FRAME + WELDED REINFORCED BRACKETS IN BEHINDE STEPS TO HELP STOP THEM FROM BENDING IN, INVESTERGATED LEAK ON AUTO LUB POT CANT FIND LEAK LOOKS LIKE OVER FILLED CLEANED UP MESS TOLD DRIVER TO KEEP ????? IT IF LEAKS AGAIN TOR & PORTIT	NICK PENNY - 53644
17/11/17	9719	REPLACE HYD HOSE FOR DIPPER RAM + O RING SEALS, TESTED A/C SYSTEM, NO GAS RECOVERED, PRESSURIZED SYSTEM WITH NITROGEN, FOUND LEAK ON, CONDENSOR NEW PART NEEDED HELPED WITH SERVICE CHANGED AIR FILTERS HYD FILTERS X 3 HYD BREATHER FILTER, FUEL TANK BREATHER FILTER, CABIN FILTERS X 2 FIXED WATER LEAK ON BACK OFF ENGINE (NEW HOSE CLIP)	NICK PENNY - 55808
20/11/17	9719	REPLACED HEADERTANK FILLER CAP, REPLACED A/C CONDENSOR RECHARGED GAS AT 1000G OUV 5ML OIL RAN TESTS 5 BAR ON BOTH LINES WHEN NOT RUNNING, 8 BAR ON HIGH PRESSURE	NICK PENNY - 55809

Machine History

		2 BAR ON LOW PRESSURE WHEN PUMP ENGAGED ALL OK. NO MORE LEAKS FOUND DRILLED OUT SNAPPED OFF BOLT ON UNDER CARRAGE GARD PUT IN NEW BOLT.	
17/11/17	9719	1000HR SERVICE OILS CHANGED – ENGINE, FINALS, SLEW X2 FILTERS CHANGED – ENGINE X 3, AIR X2, CAB X2, HYDX5, PILOT, BREATHERS X2 SAMPLED – ENGINE, FINALS, SLEWS, HYD ALL LIGHTS + LEVELS CHECKED BATTERIES – SEALED COOLANT - 46	A.RUNNACLES - 55773
12/12/17	9846	REPLACE FUEL FILTERS (FUEL BLOCKED WARNING ON DASH)	R.MERRYDEW - 56213
19/12/17	9875	FIT AMBER BEACON REPLACED WIRE AND FIT BULB FOR REAR LIGHT.	L MULLINS - 55422
13/01/18	???	REPLACED O-RING LEFT HAND BUCKET RAM HOSE 2X WORK LIGHTS TO REAR OF MACHINE	L.MULLINS - 55425
29/01/18	10018	CHANGED + SAMPLED SWING OILS	A RUNNACLES - 56810
29/01/18	10018	CHECK OUT SLEW NOSE. DRAIN OIL IN ??? GEAR BOXES SAMPLE ETC REMOVE BROKEN BOLTS X3 FROM SPOOL BLOCK PEDISTAL/ FRAME REBOLT	M. HILLMAN - 56657
02/02/18	10023	REPLACE FUEL FILTERS X2 250HR SERVICE TIGHTEN UP BUCKET BOLTS REMOVE BROKEN STUDS X 4 FIT STEP TO TRACK FRAME.	M. HILLMAN - 56656
16/02/18	10127	REMOVE WIPER ARM CLEAN WIPERS UP RESET ARM REPLACE LOWER WIPER BLADE REPAIRS TO WASH SYSTEM REMOTE TANK CHECK PUMPS REMOVE ALL BELLY PLATES REPAIRS TO PIPE CLEAN / BLOW OUT JETS ECT REPAIRS TO LH CAB LAMP	M.HILLMAN - 56667
24/02/18	10175	DRAINED DIESEL TANK REMOVED INSPECTION PLATE CLEANED INSIDE OF TANK + REPLACED SUCTION STRAINER REFIT INSP PLATE WITH NEW O RING FITTED 15GAL DIESEL REPLACED FUEL FILTERS & PRIMED RUN FOR 30MINS REPLACED WIND WASHER PUMP	J.WYATT - 56294
12/02/18	10094	CHECK OUT FRONT WIPER PROBLEM AJUST WINDSCREEN TRIP SWITCH CHECK HYD VALVES ON RH SWINS MOTORS DAMP / HYD OIL REPLACE FRONT CAB LAMP BULB	M.HILL - 56664
16/04/18	10418	CHECK ROUND PUMP UP LH TRACK REPLACE HYD COOLING FAN PIPES X 2	M.HILLMAN - 56687

Machine History

		MOVE ???? PIPES UNDER SPOOL BLOCK.	
12/04/18	10409	500HR SERVICE ENG OIL CHANGED + SAMPLED HYD SAMPLED SLEW SAMPLED FILTERS CHANGED – ENG X3, FUEL X2 CHANGED BULB ADJUST DOOR CATCH, REPLACE MISSING BOLTS ON TOP PANELS BATTERIES – CHECKED COOLANT - 46	A RUNNACLES – 57 310
08/06/18	10715	REPAIRS TO GREASE UNIT STOP OUT PUMP / CLEAN REASSEMBLE CHECK FOR WORKING	M HILLMAN - 59159
24/05/18	10672	REPAIRS TO PUSH LINE MAIN SUPPLY PIPE REMOVE CAB BELLY PLATES AND CHECK UAB AMOUNTS PUMP UP 12H TRACK	M HILLMAN - 59158
14/06/18	10745	750HR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED BATTERIES – CHECKED COOLANT - 46	A RUNNACLES - 59300
???	10743	CRACK REPAIRS ON BOOM ABOVE RAMS X2	M HILLMAN - 59161
27/07/18	10927	REMOVE MAIN LIFT RAM PIN DROP RAMS DOWN ????????? WELD REPAIRS INSIDE OF BOOM PIN MOUNT. FIT INFORCING GUSSETS TO INSIDE OF BOOM + CRACK REPAIR TO BOSS. FIT OUTER PLATES TO BOOM ???? AS PER VOLVO RECOMMENDATIONS REASSMBLE RAMS ??	M HILLMAN - 59171
16/08/18	11048	REPLACE MAIN TRACKING PIPES X 4 REPAIRS TO BELLY PLATES ECT TOP UP HYD OK. ETC	M HILLMAN - 59177
13/09/18	11202	1000HR SERVICE + INSPECTION OILS CHANGED + SAMPLED – ENG, FINALS, SLEWS + SAMPLED HYD FILTERS CHANGED – ENG X3, FUEL X2, AIR X2, CAB X2, HYD X5, BREATHERS X2 LIGHTS AND LEVELS CHECKED BATTERIES – CHECKED COOLANT – 46 LIGHTS + LEVELS CHECKED BATTERIES – CHECKED COOLANT – 46 ENG COMMENTS:	A RUNNACLES - 58524

Machine History

		DIPPER CRACKED BUCKET CRACKED + WATER METAL WORN THROUGH	
06/10/18	11335	REPAIRS TO GREASE PIPES X4 RE SHIM BUCKET MAIN PIN REPLACE PUSH LINKS SEALS X2	M HILLMAN - 59193
26/10/18	11451	250 HR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED	A RUNNACLES - 61240
10/11/18	11510	REPLACE BUCKET WELD REPAIRS ON SPARE BUCKET REPLACE TEETH ON SPARE BUCKET REPLACE MAIN GREASE FEED PIPE ON PUSH LINK. WELD REPAIRS ON SPARE BUCKET (BL) CHECK ROUND EDGE	MH, BL, NP - 58023
26/10/18	11451	FIT (HYD HOSE) GREASE PIPE FROM DIPPER TO BUCKET PUSH LINK INCLUDING 3X HOSE CLAMPS. FIT DOOR HANDLE ASSEMBLY TO REAR LEFT DOOR REPAIRED DOOR CATCH. FIT 2X LED SPOT LIGHTS TO REAR OF MACHINE MADE HEAVIER BRACKETS FOR LIGHTS. REPAIRED BACK REAR RIGHT TOP LEFT SPOT LIGHT (CAB)	L MULLINS – 58418
19/11/18	11573	REFIT LARGE BUCKET	M HILLMAN – 58029
21/12/18	11746	500 HR SERVICE ENG OIL CHANGED + SAMPLED HYD SAMPLED FILTERS CHANGED – ENG X3, FUEL X2 LIGHTS + LEVELS CHECKED BATTERIES CHECKED COOLANT- 46	A RUNNACLES- 61816
22/1/19	11876	REPLACED O/G ENGINE MOUNT AND O/G ENGINE MOUNT RUBBERS FRONT AND REAR , REPLACED INLET HOSES REPAIRS OF DIPPER NEAR BUCKET	NICK PENNY-61650
22/02/19	12057	750 HOUR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST N/A BATTERIES CHECKED COOLANT – 46 ORANGE BEACON NOT WORKING	ADAM RUNNACLES -
4/4/19	12326	REPAIRS TO GREASE PIPES ON H LINK	M HILLMAN- 60081
11/07/19	12760	250 HOUR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECK COOLANT: -46	ADAM RUNNACLES
06/09/19	13093	500 HOUR SERVICE ENGINE OIL CHANGED AND SAMPLED HYDRAULIC OIL SAMPLED	ADAM RUNNACLES

Machine History

		FILTERS CHANGED: ENGINE X3, FUEL X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	
10/09/19	13112	HEATHER FAN NOT WORKING FOUND IT NEEDS NEW FAN MOTOR	NICK PENNY - 64193
13/09/19	13136	REPLACED HEATER FAN MOTOR, REPAIRED GREEN BEACON, CHECKED OIL, WATER, TIGHTENED UP BOLTS ON HYD HOSE ON DIPPER ARM, CHECKED IN AND AROUND ENGINE BAY	NICK PENNY - 64195
18/10/19	13329	750 HOUR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED, AIR.CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	ADAM RUNNACLES
17/10/19	??	REMOVE STEEL PIPE WORK LIFT RAMS FROM SPOOL ?? TO RAMS WELD REPAIRS TO FRONT REPLACE AND RUN	M HILLMAN - 64370
29/10/19	13383	REFIT BUCKET FIT NEW O RINGS AND ??	M HILLMAN - 64376
05/12/19	13587	1000 HOUR SERVICE AND INSPECTION OILS CHANGED AND SAMPLED: ENGINE, SLEWS, FINAL DRIVES AND SAMPLED: HYDRUALIC FILTERS CHANGED: ENGINE X3, FUEL X2, AIR X2, CAB X2, HYDRAULIC X5, BREATHERS X2 LIGHTS AND LEVELS CHECKED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	ADAM RUNNACLES
18/11/19	13482	REPLACE STEEL HYD PIPE SPOOL TO RAM ?? LIFT	M HILLMAN - 64391
29/11/20	13830	REPLZCER O RING ON BUCKET RAM PIPE RECONNECT ETC	M HILLMAN 62017
10/2/20	13902	250HR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED AIR CAB FILTERS CLEANED BRAKE TEST N/A BATTERES CHECKED COOLANT -46	ADAM RUNNACLES
14/02/20	13838	REPAIRS TO WASHERS ON FRONT SCREEN	M HILLMAN - 62020
17/03/20	14098	FUSE 8 REPORTED AS BLOWING, CHECK CIRCUIT TO GROUND NO SHORT DETECTED. INSTALL NEW FUSE AND TEST – OK. ARRANGE FOR MACHINE TO BE MOVED OFF LOADING PAD. INSPECT CIRCUIT, CHECK HARNESS AND DIODE IN CIRCUIT – OK. INSPECT HARNESS TO ENGINE FOUND WIRE EXPOSED AND HARNESS IN CONTACT WITH BROKEN P CLIP. CARRY OUT HARNESS REPAIR. REMOVE CAB PANELS AND INSPECT HARNESS AT REAR OF CAB AND AT SWITCH SW2704/ OK. SWITCH EXTREMELY SENSITIVE. ADVISE TO REPLACE ENGINE LIMP HOME SWITCH/E SHUTDOWN SWITCH.	SMT - 473118
10/03/20	12551	CARRIED OUT THOROUGH EXAMINATION. INVESTIGATE MACHINE FAULT. NO COMMUNICATION WITH ENGINE ECU FROM IECU AND VECU. CHECK POWER TO EECU – 0 VOLTS. INSPECT FUSE 08. FUSE BLOWN. INSTALL AMP TEST AND TEST CIRCUIT – 1 – 2- AMPS DRAW. INSTALL NEW FUSED AND ADVISE OPERATOR TO TEST MACHINE, NO	SMT - 473118

Machine History

		FUSE BLOWN OCCURRENCES DURING HEAVY MACHINE USE. NO CAUSE OF FUSE BLOWN FOUND. ADVISE TO RUN MACHINE UNKNOWN CAUSE OF FUSE FAILURE	
17/03/20	12551	CARRIED OUT THROUGH EXAMINATION, INVESTIGATE MACHINE FAULT, NO COMMUNICATION WITH ENGINE ECU FROM IECU AND VECU. CHECK POWER TO EECU – 0 VOLTS INSPECTED FUSE 08, FUSE BLOWN. INSTALL AMP TEST AND TEST CIRCUIT – 1 – 2 AMPS DRAWN. INSTALL NEW FUSE AND ADVISE OPERATOR TO TEST MACHINE, NO FUSE BLOWN FOUND. ADVISE TO RUN MACHINE UNKNOWN CAUSE OF FAILURE.	SMT VOLVO – INVOICE: 6312823
18/03/20	14098	FUSE 8 REPORTED AS BLOWING, CHECK CIRCUIT TO GROUND NO SHORT DETECTED. INSTALL NEW FUSE AND TEST – OK. ARRANGE FOR MACHINE TO BE MOVED OFF LOADING PAD. INSPECT CIRCUIT, CHECK HARNESS AND DIODE IN CIRCUIT OKAY. INSPECT HARNESS TO ENGINE FOUND WIRE EXPOSED AND HARNESS IN CONTACT WITH BROKEN P CLIP. CARRY OUT HARNESS REPAIR. REMOVE CAB PANELS AND INSPECT HARNESS AT REAR OF CAB AND AT SWITCH SW2704 OKAY. SWITCH EXTREMELY SENSITIVE. ADVISE TO REPLACE ENGINE LIMP HOME SWITCH/E SHUTDOWN SWITCH.	SMT VOLVO – INVOICE: 6312994
31/03/20	14190	500 HOUR SERVICE ENGINE OIL CHANGED AND SAMPLED HYDRAULIC OIL SAMPLED FILTERS CHANGED: ENGINE X 3, FUEL X 2 LIGHTS AND LEVELS CHECKED; AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES: CHECKED COOLANT: -46	A RUNNACLES
31/03/20	14190	REPLACE STOP SWITCH IN CAB REPLACE SENSING LIGHT ON PUMP. REPAIRS TO WASHERS.	M HILLMAN - 62037
17/06/20	14550	750 HOUR SERVICE: CHANGED FUEL FILTERS X 2. LIGHTS AND LEVELS CHECKED; AIR / CAB FILTERS CLEANED. BRAKE TEST: N/A BATTERIES: CHECKED. COOLANT: -46 DEG C	A RUNNACLES.
13/08/20	14869	1000 HOUR SERVICE AND INSPECTION OILS CHANGED AND SAMPLED: ENGINE, SLEWS, FINAL DRIVES AND SAMPLED: HYDRAULIC FILTERS CHANGED: ENGINE X3, FUEL X2, AIR X2, CAB X2, HYDRAULIC X6, HYDRAULIC BREATHER LIGHTS AND LEVELS CHECKED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	ADAM RUNNACLES
13/08/20	14869	REPLACE STEEL HYD PIPES FOR MAIN LIFT RAMS FRONT SUPERSTRUCTURE X2 REPAIRS TO GREEN FLASHING LAMP	M HILLMAN - 73838
24/09/20	15107	250 HOUR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	ADAM RUNNACLES
18/09/20	15050	REPLACE MAIN HYD PUMP PIPE TO SPOOL BLOCK TIGHTEN VARIOUS NUT AND BOLTS	M HILLMAN - 74552

Machine History

09/10/20	15195	REMOVE MAIN BUCKET FROM MACHINE AND FIT SPARE ONE. BUCKET SENT BACK TO FORD FOR REPAIR CHECK LIGHT ON TOP OF CAB. LIGHT U/S. FIT 2 NEW LED LAMPS ALL OK	S MARSH/BRAD - 74158
26/10/20	15299	REPLACED A SWING MOTOR HOSE ASSY ON SITE FOR CUSTOMER	FINNING – AB4755
06/11/20	15372	500 HOUR SERVICE ENGINE OIL CHANGED AND SAMPLED HYDRAULIC OIL SAMPLED FILTERS CHANGED: ENGINE X3, FUEL X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	ADAM RUNNACLES
13/11/20	15382	REMOVE 1 RE FIT SWING MOTORS X2 REPLACE MAIN LIFT PIPE ON RAM RH REPLACE GREEN LAMP	M HILLMAN - 74582
07/01/21	15646	CHANGED BUCKET WITH B WHITTOCK SHIMMED AS REQUIRED	J WYATT
18/01/21	15691	750 HOUR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	ADAM RUNNACLES
09/03/21	?	REPAIRED AND WELDED CRACKS ON THE STEPS ATTACHED TO THE TRACK FRAME. WELDED 3 60MM PLATE IN REPLACE OF THE BOTTOM STEPS	A HAMILTON - 73996
09/03/21	15803	REPAIR REVERSING BEEPER WIRING, FIT NEW BEEPER AND BLUE FLASHING LIGHTS. REPAIR WIRE ON REAR SPOT LIGHTS, REPAIR STEPS AND HANDRAILS. INSPECT THE MACHINE. PUT ON ONE COUNTERWEIGHT BOLT, PUT ON TRACK PAD BOLT A BIT OF PLAY IN THE BOTTOM PINS ON BOOM RAMS L AND R SIDE	K GEORGIEV - 65226
09/03/21	15831	FITTED MAIN PIN FOR DIPPER RAM	N PENNY M PALMER
24/02/21	??	BLOCK MACHINE AND LET DOWN TRACKS. REMOVE BOTTOM ROLLERS. RETAP HOLES AND REMOVE SNAPPED BOLTS. LIFT ON NEW ROLLERS WITH FORK LIFT. ? AND TORQUE UP ROLLER BOLTS. FIT NEW HYDRAULIC TANK CAP. ON ONE SIDE SPLIT TRACKS WITH TRACK PIN PRESS AND RUN TRACKS OFF SPROCKET. REMOVE TRACK MOTOR OFF THE BACK OF SPROCKET AFTER MARKING ALL PIPES WITH COLOURED CABLE TIES. STRIP APART ? HUB, CHANGE SEALS AND CHANGE OUTER ?. CARRY OUT INSPECTION	J TIBBS - 65035
16/04/21	15873	REFIT BUCKET REPAIR GREASE PIPE ON PUSH LINK	M HILLMAN - 65855
24/04/21	??	REMOVED BENT SECTION OF WALK WAY AND REPLACED O RING SEAL ON SLEW MOTOR REPAIRING OIL LEAK	N PENNY
26/04/21	??	REPLACED ORANGE BEACON AND WIPERS	N PENNY
29/04/21	15915	STRAIGHTENED OUT PARTS OF STEP AND FITTED NEW BRACKET AND SECTION OF WALK WAY	N PENNY
08/05/21	15949	REPLACED HYD HOSE AND SEAL ON BUNG AT TOP OF SLEW MOTOR TOPPED UP HYD OIL LEVEL	N PENNY
15/05/21	15987	1000 HOUR SERVICE AND INSPECTION OILS CHANGED AND SAMPLED: ENGINE, SLEWS X2, FINAL DRIVES AND SAMPLED: HYDRAULIC FILTERS CHANGED: ENGINE X3, FUEL X2, AIR X2, CAB X2, HYDRAULIC	ADAM RUNNACLES

Machine History

		X5, HYDRAULIC BREATHER LIGHTS AND LEVELS CHECKED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	
17/05/21	??	REPAIRED OIL LEAK 22/05/21 REPLACED O RING SEALS ON SLEW MOTOR AGAIN	N PENNY
25/05/21	16045	REPLACED BUNG ON SLEW MOTOR 26/05 REPLACED 2X GREASE PIPES ON PUSH LINK	N PENNY
01/06/21	?	FITTED NEW BOLT TO HOLD IN BUCKET PIN	N PENNY
22/06/21	16122	REPLACED MAIN FEED HOSE FROM PUMP TO SPOIL BLOCK	N PENNY
17/06/21	16097	REALIGNED BUCKET PIN AND FITTED RETAINING BOLT	N PENNY
15/07/21	16283	250 HOUR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	ADAM RUNNACLES
18/08/21	??	WELDED CRACKED ON THE DIPPER BOOM WELDED CRACK ON THE BOTTON OF THE MAIN BOOM REPLACED BROKEN CUTTING EDGE SHROUD ON THE BUCKET WELDED CRACKS IN THE CUTTING EDGE ON THE BUCKET WELDED CRACKS ON THE CUTTING EDGE SHROUDS ON THE BUCKET WELDED CRACKS AROUND THE BUCKET BOSSES	A HAMILTON - 65774
20/08/21	16427	FIT NEW HYD HOSE ON PUMP TOP UP HYD OIL 46. 80 LRS	P LINES – 66106
19/08/21	16430	REFIT BUCKET NO CHIMS FITTED AS NO NEW ONES SUPPLIED	M PALMER J WYATT
20/09/21	16590	REFITTED 2X BUCKET TEETH	N PENNY
28/09/21	16639	500 HOUR SERVICE ENGINE OIL CHANGED AND SAMPLED HYDRAULIC OIL SAMPLED FILTERS CHANGED: ENGINE X3, FUEL X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED GREASED SWING BEARING BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -37	C DREDGE
??	16868	250 HOUR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -34	C DREDGE
18/11/21	16900	FITTED 7X HYD HOSES TOPPED UP LEVEL AND BOLTED GREASE BLOCK BACK ON BOOM REPAIRED GREASE PIPE ON PUSH LINK	N PENNY
04/11/21	??	REPAIRED GREASE PIPE TO PUSH LINK	N PENNY
11/11/21	16888	REPLACED BATTERIES	N PENNY
20/01/22	17208	1000 HOUR SERVICE AND INSPECTION OILS CHANGED: ENGINE, FINAL DRIVE, SLEW MOTOR AND SAMPLED: HYDRAULIC, ENGINE FINAL DRIVE, SLEW MOTOR FILTERS CHANGED: ENGINE OIL, HYDRAULIC, AIR, CAB, FUEL LIGHTS AND LEVELS CHECKED	R RODD

Machine History

		SERVICE BRAKE TEST: N/A BATTERIES CHECKED COOLANT: N/A	
20/01/22	17208	REPAIRED COOLANT LEAK UNDER CAB AND ON BOTTOM HOSE	N PENNY
07/02/22	17309	REPLACED BUCKET WITH SPARE ONE – CRACKED	J WYATT B WILLIAMS - 66893
08/02/22	17244	REMOVED CRACKED BUCKET – SENT TO YARD FITTED REPLACEMENT BUCKET	J WYATT
16/02/22	17320	REPLACE BUCKET TEETH	N PENNY
26/02/22	17386	REPAIRED COOLANT LEAK	N PENNY
03/03/22	17447	250 HOUR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED, AIR/CAB FILTERS CLEANED BRAKE TEST: N/A BATTERIES CHECKED COOLANT: -46	R RODD
08/03/22	??	REPAIRED COOLANT LEAK	N PENNY
14/03/22	17521	REPLACED HORNS 19/03 REPLACED BUCKET	N PENNY
04/04/22	14098	HAVE REMOVED AND REPLACED BROKEN COPPER INJECTOR SLEEVES. HAVE RETURNED TO SITE AND CLEANED ENGINE BLOCK AND ASSOCIATED PARTS. MACHINE IS PREPPED FOR ENGINE REASSEMBLY	SMT – W545101
05/04/22	14098	FITTED CYLINDER HEAD TO MACHINE. TIMED ENGINE AND FITTED CAM SHAFT AND DAMPERS. FITTED INJECTORS AND SEALS. FITTED ROCKER SHAFT AND CARRIED OUT FULL TOP END SETUP. REASSEMBLED ENGINE AND ASSOCIATED PARTS. WILL RETURN TO COMPLETE AND RUN UP MACHINE	SMT – W545101
07/04/22	14098/	COOLANT SYSTEM OVER PRESSURISING. INJECTOR SLEEVES REQUIRE REPLACING. WHEN REMOVING SLEEVES, THE TIPS OF SLEEVES SNAPPED OFF IN CYLINDER HEAD. REMOVED CYL HEAD & DRILL OUT SNAPPED COPPER TIPS. FITTED NEW SLEEVES. REFITTED CYL HEAD WITH NEW HEAD GASKET. REASSEMBLED M/C & TIMED ENGINE. REFITTED ORIGINAL INJECTORS WITH NEW O RINGS. CARRIED OUT FULL TOP END SETUP ON ROCKER SHAFT. FITTED EXHAUSE MANIFOLD WITH NEW GASKETS. REASSEMBLED M/C. RUN UP & HOT TESTED, NO LEAKS FOUND & ENGINE RUNNING SMOOTHLY.	SMT – 473118.
12/04/22	17584	REPLACED COOLANT TEMPERATURE SENSOR	J WYATT
08/04/22	17579	REPLACED FAN BELTS REPLACED CAMSHAFT SPEED SENSOR	J WYATT
19/04/22	17629	REPLACED MISSING BOLT ON BUCKET PIN	NICK PENNY
03/05/22	17564	REPLACED ENGINE WIRING LOOM REPLACED CRANKSHAFT SPEED SENSOR REPLACE CRANKSHAFT PRESSURE SENSOR REPLACED STARTER MOTOR REPLACED ENGINE OIL HOSE FROM DUMMY FILTER HEAD TO REMOTE FILTER HEAD. TOPPED UP ENGINE OIL.	J WYATT
30.05.22	17836	FIT NEW BUCKET PIN RETAINING BOLT	J WYATT
28.05.22	17830	REPLACED SEAT BELT AND BUCKLE	J WYATT
08.06.22	17883	500 HOUR SERVICE ENGINE OIL CHANGED AND SAMPLED HYDRAULIC OIL SAMPLED	RYAN RODD

